



## Grouped Reports: Vehicle Fires

### Dangerous Conditions

- [05-447](#) Magnesium fire in a pick-up compartment.
- [05-449](#) Fully involved vehicle with nitrous oxide tank (unknown to firefighters) in trunk.
- [05-460](#) Overhaul after a truck brake fire.
- [05-463](#) Firefighter attacked a fully involved vehicle fire without wearing gloves
- [05-537](#) Firefighter injured while breaking the side glass out of a motor vehicle.
- [05-578](#) Firefighter injured when passenger compartment flashed over.
- [06-024](#) Cautious approach and proper PPE use avoids injury after explosion at vehicle
- [06-044](#) Oil line bursts on a fully involved front-end loader fire spraying firefighters with hot oil.
- [06-242](#) Vehicle fire with report of mentally deranged driver taxes crew.
- [06-290](#) Fuel leak from extinguished vehicle fire creates hazard for firefighters
- [06-295](#) Officer smashes thumb in cab door at vehicle fire.
- [06-304](#) Water on combustible metal causes near miss at van fire.
- [06-318](#) Driver/Pump Operator extinguishes fire without proper PPE.
- [06-372](#) Hot motor oil sprays firefighter at car fire.
- [06-476](#) No SCBA used on vehicle fire.

### Exploding Parts

- [05-215](#) Air bag explosion at vehicle fire.
- [05-312](#) Hot brakes explode when water is applied.
- [05-519](#) Vehicle hood strut explodes and injures a firefighter.
- [05-545](#) Hydraulic cylinder explodes during car fire.
- [05-573](#) Spray cheese explodes during Semi-Trailer fire.
- [05-670](#) Firefighter nearly struck by exploding gas strut at vehicle fire.
- [05-678](#) Exploding lift piston strikes engine driver. Serious injury averted because of SOPs.
- [06-001](#) Air bags deploy during an auto passenger compartment fire.
- [06-102](#) Gas hood cylinder almost strikes firefighters during vehicle fire.
- [06-113](#) Hollow drive shaft explodes injuring firefighter.
- [06-185](#) Lift strut explodes during vehicle fire.
- [06-382](#) Gas filled strut under hood explodes and just misses firefighter.
- [06-467](#) Hood support strut explodes sending projectile.
- [06-527](#) Air bag deploys after extinguishment.

## Flash Fires

- [05-583](#) 2 firefighters burned during a response to a motor vehicle accident.  
Car fire flashes over during search of passenger compartment. Catches firefighter leaning in.
- [06-072](#)
- [06-303](#) Sudden burst of flames from engine compartment causes burns to personnel.
- [06-352](#) Fuel spill flashes after car fire is extinguished.

## Traffic Hazards

- [05-332](#) Firefighter nearly struck by passing vehicle at vehicle fire.
- [06-356](#) Firefighters nearly hit by semi while extinguishing car fire.
- [06-364](#) Firefighter struck by civilian vehicle at car fire.
- [06-487](#) Car nearly hits FFs working on rural road.